






FIG. 1



700220 - 90007860



1002200-30060360











FIG. 4












FIG. 7



200200-50007660

FIG. 8



T06200-30601860



FIG. 9A**FIG. 9B**

FIG. 10




FIG. 11




FIG. 12

URL <http://www.maintain.co.jp/db/input.html>

TROUBLE DB INPUT WINDOW

OCCURRENCE DATE [2000/3/15] ~ 4040

TYPE OF APPARATUS [*****] ~ 4010

SUBJECT [OPERATION ERROR (START-UP ERROR)] ~ 4030

SERIAL NUMBER S/N [465NS4580001] ~ 4020

DEGREE OF URGENCY [D] ~ 4050

SYMPTOM [LED IS KEPT FLICKERING AFTER POWER-ON]
[]
~ 4060

REMEDY [POWER ON AGAIN
(PRESS RED BUTTON IN ACTIVATION)
[]
~ 4070

PROGRESS [INTERIM HAS BEEN DONE]
[]
~ 4080

[SEND] [RESET] 4100 4110 4120

LINK TO RESULT LIST DATABASE SOFTWARE LIBRARY OPERATING GUIDE

FIG. 13

TOP SECRET//COMINT




FIG. 14

TOP SECRET - SECURITY INFORMATION

